


ZENITH RADIO CORP.

MODEL 4G800
Chassis 4E41



ANT. 37 X AT 800 KC
 39 X FROM 800 KC TO 455 KC
 10 X FROM 455 KC TO 400 M
 68 X AT 400 M
 75 MILLIWATT OUTPUT
 14 X AT 400 M
 75 MILLIWATT OUTPUT

IR5 CONVERTER
 IU4 I.F.
 IS5 DET.-AMP.
 3Q4 PWR.-AMP.

ALL VOLTAGES MEASURED FROM COMMON RETURN TO POINTS INDICATED WITH A D.C. VACUUM TUBE VOLTMETER.

D.P.S.T. SWITCH ON VOLUME CONTROL R5

I.F. FREQUENCY—455 KC
 TUNING RANGE—535 TO 1620 KC


CHANGE-OVER SWITCH SI SHOWN IN POSITION FOR A.C.-D.C. OPERATION.

⊕ DENOTES CHASSIS

117V. A.C.-D.C. 20 WATTS

⊕ DENOTES COMMON RETURN (B-)

ALL RESISTORS ±20% TOLERANCE UNLESS OTHERWISE SPECIFIED.



TUBE AND TRIMMER LOCATION

Final alignment of the 4E41 chassis should be made with the chassis installed in the cabinet. Tune in a weak station in the vicinity of 1400 KC and adjust the antenna trimmer for maximum.

ALIGNMENT PROCEDURE

OPERATION	CONNECT OSCILLATOR TO ANTENNA	DUMMY INPUT SIG. FREQUENCY	SET DIAL AT	TRIMMERS	PURPOSE
1	Converter Grid.1 MFD	455 Kc.	C14, C15, C16, C17	Align I.F.
2	One Turn Loosely Coupled to Wavemagnet.		1600 Kc.	C4	Set Oscillator to Scale --
3			1400 Kc.	C2	Adjust for Maximum.

PARTS LIST

REFERENCE NO.	DIAGRAM NO.	DESCRIPTION
CABINET ASSEMBLY		
S-13798		Handle Strip Assembly.
S-13793		Bottom Cover Assembly.
S-13847		Wavemagnet & Cover Assembly.
12-1379		Handle Support Bracket (R.H.)
12-1379		Handle Support Bracket (L.H.)
12-1380		Handle End Piece.
43-149		Front Cover Latch.
46-683		Tuning Control Knob.
46-684		Volume Control Knob.
46-685		Cabinet Front Plate.
57-1314		Chassis Bottom Plate.
59-200		Dial Pointer.
80-567		Latch Spring.
83-1416		Decorative Strip.
83-1417		Handle Strip - Rubber.
93-870		Fibre Shoulder Washer.
110-127		Grille Cloth.
199-79		Flexible Handle Sleeve.
CONDENSERS		
22-1457		2 Gang Variable. 450 V.
22-1706		.005 MFD. 500 V.
22-1669		.0001 MFD. 500 V.
22-1876		.001 MFD. 500 V.
22-1543		.001 MFD. 300 V.
22-1175		.005 MFD. 600 V.
22-326		.003 MFD. 400 V.
22-1660		.03 MFD. 400 V.
22-1655		.05 MFD. 200 V.
ON T1		1st I. F. Trans. Pri. Trim.
ON T1		1st I. F. Trans. Sec. Trim.
ON T2		2nd I. F. Trans. Pri. Trim.
ON T2		2nd I. F. Trans. Sec. Trim.
22-1443		40 MFD. Electro. 150 V.
		40 MFD. Electro. 150 V.
		200 MFD. Electro. 10 V.
		10 V.
RESISTORS		
63-1870		100 M Ohm. 1/2 W.
63-1954		10 Megohm. 1/2 W.
63-1940		4.7 Megohm. 1/2 W.
63-1856		47 M Ohm. 1/2 W.
63-1553		1 Meg. Vol. Control.
63-1961		15 Megohm. 1/2 W.
63-1912		1 Megohm. 1/2 W.
63-1933		3.3 Megohm. 1/2 W.
63-1762		300 Ohm. 1/2 W.
63-1786		1000 Ohm. 1/2 W.
63-1631		12 M Ohm. 1/2 W.
63-1824		6200 Ohm. 1/2 W.
63-1891		350 M Ohm. 1/2 W.
63-1800		2200 Ohm. 1/2 W.
63-1771		470 Ohm. 1/2 W.
63-1789		1200 Ohm. 1/2 W.
63-1564		91 Ohm. 2 W.
63-1647		1050 Ohm. 2-1/2 W.
		1050 Ohm. 2-1/2 W.
COILS AND CHOKES		
L1		Wavemagnet Assembly.
L2		Oscillator Coil Assembly.
T1		1st I. F. Transformer.
T2		2nd I. F. Transformer.
MISCELLANEOUS		
S1		Change over Switch.
SPL		3" P. M. Speaker.
T3		Speaker Transformer.
SEL		Selenium Rectifier.
OR		Selenium Rectifier.
212-4		


Zenith 4G800 Chassis 4E41

This model appears in *Volume XVII of Rider's Manuals, pages 17-1 and 17-2*. The On-Off switch #85-433 does not completely break contact on some receivers when the lid is closed, causing battery drain. To correct this condition, saw one plastic switch knob 46-736 into 1/16" lengths and place a length on the switch shaft, and then replace the knob. This will force the switch down far enough when the lid is closed to break contact and disconnect the batteries.

In some cases the calibration pointer touches the metal front of the cabinet, thus putting the gang at an a-c potential and causing a hum. To correct this condition place a fibre washer #93-323 between the pointer and the metal dial front. This fibre washer between the metal front panel and the dial pointer, completely prevents this "shorting" condition.

In very rare cases, when hum is encountered and cannot be corrected in any other manner, changing the 1S5 tube is suggested.

On later production runs the 3Q4 tube was replaced with a 3V4 tube. The circuit remains the same in this case. However, the wiring to the tube base has been altered. The 3Q4 is not interchangeable with the 3V4 because of socket connections.



Enough extra lead length should be left when replacing the wavemagnet lead on the Zenith 4G800 so that a break does not occur at the point indicated.

In some cases when the front lid of the receiver is open, the receiver will cut in and out or sometimes be entirely dead. The wire from the wavemagnet to the front door hinge may break at the hinge connection. To correct this condition, remove the handle and resolder these leads, being quite certain that solder is not allowed to run back on the antenna lead and that enough extra antenna lead is allowed for flexing to prevent breakage when the door is open as illustrated in the accompanying diagram.


Zenith 6G801, Chassis 6E40

This model appears in *Rider's Volume XVIII, pages 18-7, 18-8, and 18-10*. In some cases when microphonics are encountered they can be eliminated by replacing one or more of the tubes. The offending tube can be located by turning the set on with the volume advanced and the set tuned to an off-station position. Then gently tap each tube, the one emitting the loudest "ping" is the defective item.

Zenith 8H023, 8H034, Chassis 8C01

These models appear on *pages 15-71 to 15-74 of Rider's Volume XV*. The rushing noise that occurs when the volume control is turned to minimum is caused by a poor connection from the grid element to the grid cap of the 6S8GT tube. A hot iron and a little flux on the grid cap will remove the high-resistance solder joint.

If the f-m oscillator drifts, check for a red dot on the oscillator tuning-slug wire. If the wire is unmarked, replace with one which has a red dot. If the receiver flutters on f.m., this may be cured by installing a 22-1635, 20- μ f, 150-V capacitor and two 1/4-watt resistors, 63-583, 1000 ohms, and 63-600, 2.2 Megohms, as indicated in the accompanying diagram.



Drift in the f-m oscillator of the Zenith 8H023 may be corrected by making the changes indicated.