MODELS 450T,
451T, Ch. RE-281

The alignment procedure should be repeated in the original order for greatest accuracy. Always keep the output from the signal generator at its lowest possible value to make the AVC action of the receiver ineffective.



©John F. Rider

Courtesy Nostalgia Air