



G-250 SCHEMATIC DIAGRAM





PARTS LIST (Rotator)

- | | |
|-------------------------------|--------------------------|
| (1) Gear Mounting Plate Ass'y | (18) 3x6mm Screw (x2) |
| (2) Central Shaft Bushing | (19) Rotation Limit Arm |
| (3) Potentiometer | (20) Upper Shaft Bushing |
| (4) Motor | (21) Upper Housing |
| (5) Motor Pinion | (22) M4x14 Screw (x4) |
| (6) M4x8 Screw (x2) | (23) Mast Support Plate |
| (7) Gear Ass'y (#2) | (24) M5x12 Bolt (x4) |
| (8) Gear (#1) | (25) Cable Clamp |
| (9) Gear Ass'y (#3) | (26) Cable Clamp Screw |
| (10) Gear (#4) | (27) Upper Mast Clamp |
| (11) Pot. Divider Gear (#1) | (28) Lower Mast Clamp |
| (12) Pot. Divider Gear (#2) | (29) Cable Grommet |
| (13) 'E' Ring | (30) M5x15 Bolt (x4) |
| (14) 'E' Ring | (31) 'U' Bolt (x4) |
| (15) Internal Gear | (32) M6 Flat Washer |
| (16) Terminal Board | (33) M6 Split Washer |
| (17) Lower Housing | (34) M6 Nut |

OPTIONAL PARTS



GS-060 50mm
Thrust Bearing



GS-065 65mm
Thrust Bearing