




Circuits des Résistances

9	3x13	23	33	43	48	48'	48"	53	U										
	70	70	70	335	80	100	335	100	150	190	210								
10	17	26	27	3x29	37	45	61/62												
	410	150	150	180	180	180	405	400	280										
11	15	3x18	25	28	35/36	38	55	57	58	67	68	L	S						
	300	315	315	315	280	360	335	360	385	320	390	210	195	390	325				
12	11/12	51/52	14	16	24	34	44	N1/N2	P	3xA									
	5	5	5	5	5	5	5	500	5	370	180	130							

Circuits des Capacités

9	15	25	29	35	45	55	57	61/62											
	280	290	470	225	485	475	485	480											
10	17	27																	
	220	120																	
11	13	33																	
	265	250																	
12	43x45	48x45	48x48"	48x53	53	U													
	265	135	60	240	210	175													

Mettre le commutateur de λ sur 6.0.

" " volume contrôle au maximum

Mesurer U, le commutateur étant sur la position RV.

Pour la mesure 43x45 mettre le volume contrôle au minimum