



C47	See coils		R25	330 Ω	A9 999 00/330E
C48	Véase bobinas		R26	10000 Ω	A9 999 00/10K
	Voir bobines		R27	2.2 M Ω	A9 999 00/2M2
C49	82 pF	A9 999 04/823	R28	1 M Ω	A9 999 00/1M
C50	47000 pF	A9 999 06/47K	R29	1 M Ω	A9 999 00/1M
C51	39000 pF	A9 999 06/39K	R32	12000 Ω	A9 999 00/12K
C52	10000 pF	A9 999 06/10K			
C53	0.12 μ F	A9 999 06/120K			
C54	15000 pF	A9 999 06/15K			
C55	22000 pF	A9 999 06/22K			
C56	390 pF	A9 999 04/390E			
C57	2200 pF	A9 999 06/V2K2			
C58	100 μ F	AC 5540/100			
C59	1500 pF	A9 999 04/1K5			
C60	47000 pF	A9 999 06/47K			
C61	1500 pF	A9 999 06/1K5			
C62	2200 pF	A9 999 06/2K2			
R1	1200 Ω	49 379 78.0			
R2	1000 Ω	A9 999 00/1K			
R3	1 M Ω	A9 999 00/1M			
R4	10000 Ω	A9 999 00/10K			
R5	1000 Ω	A9 999 00/1K			
R6	1 M Ω	A9 999 00/1M			
R7	2x47000 Ω par.	A9 999 00/47K			
R8	47000 Ω	A9 999 00/47K			
R9	15000 Ω	A9 999 00/15K			
R10	560 Ω	A9 999 00/560E			
R11	1.5 M Ω	A9 999 00/1M5			
R12	1.2 M Ω	A9 999 00/1M2			
R13	47000 Ω	A9 999 00/47K			
R14	450000 Ω)	48 900 00/			
R15	50000 Ω)	DL 50K + 450K			
R16	15000 Ω	A9 999 00/15K			
R17	0.1 M Ω	A9 999 00/100K			
R18	10 M Ω	A9 999 00/10M			
R19	56000 Ω	A9 999 00/56K			
R20	56000 Ω	A9 999 00/56K			
R21	3300 Ω	A9 999 00/3K3			
R22	1000 Ω	A9 999 00/1K			
R23	50000 Ω)	48 900 00/			
R24	450000 Ω)	DL 50K + 450K			

BX 638 Z



R15089

Fig.1








Fig.3 sk7 R15091



S:	1.2.3.4.5.6.7.8.9.10.11.12.13.14.15.16.	25.	23.17.18.19.20.21.24.	32.35.37.	26.27.28.29.30.31.32.33.34.35.36.38.39.40.41.42.	43.44.45.46.	51.47.48.49.50.
C:	8.10.12.13.14.15.16.17.	19.21.22.24.6.7.	27.4.15.16.62.	29.30.31.34.35.36.	40.42.33.37.39.43.44.	45.50.46.	47.21.48.49.50.51.52.53.54.55.56.57.
R:	2.	1.3.	4.5.	32.	7.6.0.9.26.	10.	27.13.14.15.16.28.29.17.18.20.19.23.24.21.22.25.




Fig.5

