

SYMBOLS FOR BASE DIAGRAMS: Dp—Diode Plate; F—Filament; Fc—Filament Center; G—Grids numbered according to their position from the cathode; H—Heater; Hc—Heater Center; Ht—Heater Tap; IC—Internal Connection; DO NOT USE; J—Jumper; K—Cathode; NC—No Connection; P—Plate; R—Ray Control; S—Metal Shell; SA—Starter Anode; T—Target; XS—External Shield; □—Top Cap; ■—Locating Key.