




SOCKET VOLTAGE CHART


NOTES:-

1. THESE ARE BOTTOM VIEWS OF SOCKETS.
2. MEASURE VOLTAGES FROM SOCKET LUGS TO CHASSIS (-B, -A, GROUND).
3. THESE VOLTAGES MEASURED USING AN ELECTRONIC VOLTMETER.
4. W.J. - WIRING JUNCTION.
5. NC - NO CONNECTION.
6. SOCKET VOLTAGE TOLERANCE, 10%.



Crosley Corp.

The material presented on this page has been prepared by and is printed through the courtesy of THE CROSLEY CORP.



SCHEMATIC DIAGRAM— MODELS 46FA and 46FB