

LEGEND FOR MODELS 30-B, C AND D

$C^1 = .00035 \text{ mfd}$	$C^8 = .00015$	$C^{14} = 2$	$R^6 = 3,000 \text{ ohms}$	$R^{12} = 1500 \text{ ohms}$
$C^2 = .00035 \text{ mfd}$	$C^9 = .1$	$R^1 = 400 \text{ ohms}$	$R^7 = 60,000$	$R^{13} = 800$
$C^3 = .00035$	$C^{10} = .1$	$R^2 = 400$	$R^8 = 2,000$	$R^{14} = 2 \text{ meg}$
$C^4 = .00035$	$C^{11} = .1$	$R^3 = 400$	$R^9 = 10,000$	
$C^5 = .00015$	$C^{12} = .1$	$R^4 = 3,000$	$R^{10} = 300,000$	
$C^6 = .0075$	$C^{13} = 4$	$R^5 = 3,000$	$R^{11} = 3,500$	

SEE DATA SHEET . I.

SILVER MARSHALL

