



1934 - 35  
Instr. 500 n p.v.

	1	2	3
KG			
OG	X	X	X
LG	X		
P.U.			

Zekering : 110-130V = 0.5A  
Fusible : 150V = 0.35A  
220-240V = 0.26A

