


TO CONNECT TO J1 OF R3A & PIN 1 OF PPI

J1

R36 CODE DO



6. For under chassis tests, etc. remove the four (4) screws securing chassis to board. Remove board.

6. **\*\* INDICATE COLOR DOT ON SPE**

6. For under chassis tests, etc. remove the four (4) screws securing chassis to board. Remove board.