


Zenith Radio Chassis 5Z21, Models HFZ18R and HFZ19E



In the event a chassis must be removed and speaker wires disconnected, it is imperative that when replacing the wires on the terminal board of the amplifier chassis that proper color coding be observed; brown wires must go to the terminals marked 'brown', black wires must go to the terminals marked 'black', and wires with the orange tracer on their edge must go to the terminals marked 'orange'. In addition to this, it is important that the wires connected to the terminals on the woofer speaker be replaced exactly as they are removed since to reverse one pair of parallel leads will cause these speakers to be out of phase with resulting poor tonal quality.