




Circuits des Résistances

9	13	23	33	38'	37	43	38	61	62	P	U								
	80	130	90	180	225	85	340	450	450	185	500								
10	17	27	47																
	275	285	410																
11	18	28	48	67	68	L	S												
	450	450	435	430	430	435	420												
12	15	25	35	11/12	---	41/42	N1	N2											
	10	10	10	10	---	10													

Circuits des Capacités

9	A																		
	340																		
10	18	28	17	27	37	47	48												
	390	390	260	300	300	350	330												
11																			
12	38'	38	38x43	13	33	43													
	170	290	65	365	170	70													

Placer le commutateur de λ sur G.O. - C.V au maximum

Sensibilité maximum

Potentiomètre du volume au maximum