




BX 253 U

C81	0,1	μF	A9 999 06/100K	S21)		
C82	10000	pF	A9 999 06/10K	S22)		
C83	4700	pF	A9 999 04/4K7	S23)		WE 120 82.0
C85	100	μF	A9 999 10/100	S24)		
C86	10000	pF	A9 999 06/V10K	S25)		
C88	4700	pF	A9 999 06/4K7	S25a)		A3 117 83.0
C90	4,7	pF	A9 999 06/4E7	S26)		
S1)				S26a)		
S2)	ferroxcube		kraal	S27)		
S3)	ferroxcube		perle	S28)		WE 120 83.0
S4)	ferroxcube		bead	S29)		
S10)				S30)		
S10a)			A3 115 77.0	S31)		WE 120 66.0
S12)				S32)		
S13)				S33)		
C52)	47	pF	WE 120 86.0	S34)		WE 120 78.0
C53)	47	pF		C43)	195	pF
S14)				C44)	195	pF
S15)			WE 111 40.0	S35)		
S15'a)				S36)		WE 120 85.0
S16)				C45)	15	pF
S16a)	220	pF		C46)	15	pF
C16)				S38)		
S17)				S39)		WE 120 78.0
S17')				C58)	195	pF
S18)				C59)	195	pF
S19)				S40)		
S20)			WE 120 84.0	S41)		
				S42)		WE 120 70.0
				S42')		
				C60)	10	pF
				C62)	47	pF
				S45)		
				S46)		WE 151 31.0
				S47)		

WM/MZ



S:	4,							A.		B, C.
C:	4,	85,	76, 79, 84, 80,	73,	82, 72, 81, 75, 74,			71, 70, 3, 27, 25, 49, 70,	39, 29,	
R:		47, 47, 48, 55, 49,		42,	50, 56,	51, 37, 29, 40,	38,		24, 41,	34,



BX 253 U

II

C.	D.	E, F, G.	16, 16', 17, 18, H, J, 3, 10, 10', 12, 14, 14', 15, 15',
39, 29, 65, 64, 68, 37, 33, 63, 30, 47, 61, 28, 31, 32, 55, 50, 11, 88, 48, 36, 69, 24, 77, 7, 40, 11, 22, 18, 23, 14, 16, 19, 12, 1, 2, 17, 15, 20, 10, 8, 90, 5, 13, 9,	1, 34, 33, 21, 36, 30, 22, 28, 23, 27, 20, 26, 16, 17, 10, 14, 13,		

