


PHILIPS *Service*

TV

21CX 282A-01



21CX282A-01

Op enkele uitzonderingen na is deze ontvanger gelijk aan de 21TX280A-00 maar in een console-uitvoering.

Elektrisch

R52	300 Ω	was	916/GE300E	wordt	} 300 Ω + 50 k Ω	E099BG/AE31+06
R117	50 k Ω	"	916/GE50K	"		
R149	20 k Ω	"	E0982Z/12	"		
R198	2 M Ω	"	916/GE2M	"	} 20 k Ω + 2 M Ω	E0992Z/02
R81	200 k Ω	"	916/GE200K	"	} 200 k Ω	B1 514 88
C84	27 pF	"	904/27E	"		
S14		"	AD 3700 AM	"		
						AD 3800 AM

Mechanisch

Masker		was	A3 793 85	wordt	A3 794 06
lasplaat		"	A3 667 41	"	A3 531 65
Cap op achterwand		"	P5 280 18/159	"	P5 280 77/280
Druknoppenunit		"	A3 791 74	"	A3 298 10
Kanalenkiezerknop		"	A3 782 99	"	A3 783 95
Knop, fijnregeling		"	A3 782 97	"	A3 783 99
Systeemschakelaar		"	A3 783 46	"	A3 784 00
Volumeregelaar		"	P4 485 59/159	"	A3 783 97
Verticale stabiliteit		"	"	"	P5 260 47/159
Contrastregelaar		"	"	"	P5 260 47/159
Horizontale stabiliteit		"	"	"	A3 783 73
Toonregelaar		"	"	"	A3 783 73

De wijzigingen zijn toegevoegd.

SERVICE INFORMATION										
---------------------	--	--	--	--	--	--	--	--	--	--

Copyright Central Service Division N.V. PHILIPS' GLOEILAMPENFABRIEKEN, Eindhoven

Confidential Information for Philips Service Dealers

