

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

SYMBOLS FOR BASE DIAGRAMS: Dp—Diode Plate, F—Filament, Fc—Filament Center, G—Grids numbered according to their position from the cathode; H—Heater, Hc—Heater Center, Ht—Heater Tap, IC—Internal Connection, DO NOT USE, J—Jumper, K—Cathode, NC—No Connection, P—Plate, Rc—Ray Control, S—Metal Shell, SA—Starter Anode, T—Target, XS—External Shield, □—Top Cap, ■—Locating Key.