




T.			U_f		U_{a1}	U_{a2}	U_{a3}	U_g				
			V	A					V	V	V	V
AW 36-20	Mul	1	6,3	0,3	300	-55 ÷ -145	12000	-40 ÷ -80	$12 \frac{1}{2}$	318		
AW 36-21	Mul	1	6,3	0,3		410	-500 ÷ +500	14000			0 ÷ -150	maximum
AW 36-80	eur	1	6,3	0,3	300	-100 ÷ -200	10000	-40 ÷ -80	13	330		
					300	-70 ÷ -230	12000	-40 ÷ -80				
					500	-500 ÷ +500	14000	0 ÷ -150			maximum	
CME 1402	Maz	2	12,6	0,3	300	12000	100	-30 ÷ -72	13	330		
					400	14000	-500 ÷ +500	maximum				
C 14 PM	Bri	2	6,3	0,3	300	16000	300	-33 ÷ -77	$12 \frac{29}{32}$	323		
					500	18000	-500 ÷ +1000	maximum				
MW 36-44	eur	3	6,3	0,3	250	0 ÷ 250	12000	-37 ÷ -65	$12 \frac{17}{32}$	318		
					250	0 ÷ 250	14000	maximum				
14 ACP 4	Hyt	2	6,3	0,6	125	10000	-50 ÷ +350	-23 ÷ -67	13	330		
					200	14000	maximum					
14 ATP 4	RCA	2	8,4	0,45	300	10000	0 ÷ -400	-25 ÷ -69	13	330		
					400	14000	0 ÷ -400	-31 ÷ -90				
					500	14000	-500 ÷ +1000	+2 ÷ -140			maximum	
14 GP 4	amer	4	6,3	0,6	300	2170 ÷ -2940	12000	-33 ÷ -77	$12 \frac{3}{8}$	314,3		
14 GP 4 A	amer	4	6,3	0,6			500	14000			maximum	$13 \frac{5}{8}$
14 HP 4	amer	2	6,3	0,6	300	12000	-48 ÷ -265	-28 ÷ -72	$12 \frac{1}{2}$	318		
					300	14000	-55 ÷ -310	-28 ÷ -72				
					500	14000	-500 ÷ +500	0 ÷ -125			maximum	
14 NP 4	amer	2	6,3	0,6	300	12000	-50 ÷ +350	-50	$13 \frac{1}{16}$	331,8		
14 NP 4 A	TS	2	6,3	0,6			500	14000			maximum	
14 QP 4	amer	2	6,3	0,6	250	9000	-50 ÷ +250	-24 ÷ -64	$12 \frac{1}{2}$	318		
14 QP 4 A	amer	2	6,3	0,6			500	11000			-500 ÷ +1000	0 ÷ -180
14 RP 4	amer	2	6,3	0,6	300	10000	-50 ÷ +350	-26 ÷ -70	13	330		
14 RP 4 A	amer	2	6,3	0,6			300	10000			-70 ÷ +470	-26 ÷ -70
							400	14000			-500 ÷ +500	0 ÷ -110
14 SP 4	amer	2	6,3	0,6	300	12000	-48 ÷ +264	-50	$12 \frac{15}{16}$	328,6		
					500	14000	maximum					
14 WP 4	amer	2	6,3	0,6	300	12000	-50 ÷ +350	-50	13	330		
					500	14000	maximum					
14 XP 4	amer	2	6,3	0,45	300	12000	-50 ÷ +350	-50	$12 \frac{15}{16}$	328,6		
14 XP 4 A	amer	2	6,3	0,45			400	15000			maximum	
14 ZP 4	amer	2	6,3	0,6	300	12000	0 ÷ +450	-27 ÷ -72	13	330		
					500	14000	-500 ÷ +1000	0 ÷ -140			maximum	
35 ЛК 2 Б	СССР	2	6,3	0,3	300	12000	-100 ÷ -425	-30 ÷ -90	$12 \frac{13}{16}$	325		
					500	14000	maximum					

T.	Fig.	A	B	C	D	E	F	G
		mm	mm	mm	mm	mm	mm	mm
AW 36-20	1	318	217	288	318	236	175	36,5
AW 36-21	1	318	217	288	318	236	175	36,5
MW 36-44	1	318	217	288	320	241	192	37
C 14 PM	1	323	218	291	321	240	193	37,5
14 GP 4	1	314	216	289	321	236	184	36,5
14 HP 4	1	318	216	289	321	236	184	36,5
14 QP 4	1	318	216	289	321	236	175	36,5
14 RP 4	1	330	241	306		195	165	36,5
14 SP 4	1	328	240	304		195	165	36,5
14 WP 4	1	330	241	306		195	140	36,5
14 XP 4	1	328	241	306		195	165	36,5
14 ZP 4	1	330	241	306		195	139	36,5

Fig.1

