


Sears, Roebuck & Co. Models 5732 and 5732-B Factory Nos. 109.371 and 109.371-1

These receivers are alike except that the early model C13 is .001 mfd. and C9 is .002 mfd. Also the connection from C13 was connected to the volume control side of C9.



$M = 1,000 \Omega$