


# TRAVLER



**NOTES:**

1. X INDICATES START OF VOICE COIL MARKED BY RED DOT,  
REVERSE PHASING OF SPEAKERS WILL CAUSE LOSS OF BASS.
2. REVERSE PHASING OF FEEDBACK WILL CAUSE AMPLIFIER TO OSCILLATE.
3. POLARIZE A.C. PLUG FOR MINIMUM HUM.
4. RESISTORS TO BE 1/2 WATT UNLESS OTHERWISE SHOWN.
5. CAPACITORS TO BE IN MMF. IF SMALLER THAN .005 MF.