



Operation	Connect Test Oscillator to	Dummy Antenna	Set Test Oscillator to	Band	Set Dial At	Adjust Transmitters	Purpose
1	Converter Grid	.5 mmfd.	455	—	600	A B C D	I F Alignment
2	Converter Grid	.5 mmfd.	455	—	600	E	Adi. Trap Minimum
3	Single Turn Loop Coupled Loosely to Wave Magnet	—	1400	—	1400	F	Set Osc. to Scale
4		—	1400	—	1400	G	Alignment of Antenna

\*Gnd of test osc. connected to No. 8 pin of ILA6 socket