



| VALUES OF C |                |                |
|-------------|----------------|----------------|
| MULTIPLIER  | C <sub>1</sub> | C <sub>2</sub> |
| X1          | .05            | .5             |
| X10         | .005           | .05            |
| X100        | 500            | .005           |
| X1000       | 47             | 500            |

| VALUES OF R |                |      |                |      |                |      |                |
|-------------|----------------|------|----------------|------|----------------|------|----------------|
| DIAL        | R <sub>1</sub> | DIAL | R <sub>1</sub> | DIAL | R <sub>2</sub> | DIAL | R <sub>2</sub> |
| 10          | 100K           | 60   | 16.7K          | 1    | 1 Meg.         | 6    | 163K           |
| 20          | 50K            | 70   | 14.9K          | 2    | 510K           | 7    | 139K           |
| 30          | 33.3K          | 80   | 12.5K          | 3    | 330K           | 8    | 122K           |
| 40          | 25K            | 90   | 11.1K          | 4    | 240K           | 9    | 109K           |
| 50          | 20K            | 100  | 10.0K          | 5    | 190K           | 10   |                |