

Service
Service
Service

Product Service Group CE Audio

Service Information

Already published Service Information :

Correction to Service Manual:

The Circuit diagram and Layout diagram of Control Board are not correct. Please refer to the attached updated diagrams.

Circuit Diagram	Page 9-4
Layout Diagram	Page 9-5

PCS 107 337



