



MODEL X825



THE RECEIVER
MODELS 720
AND 721 DO
NOT USE THE
EXTERNAL,
CHASSIS
GROUND CON-
NECTION OR
THE TONE CON-
TROL, SHOWN
IN PHANTOM.
OTHERWISE
THE SCHEMATIC
IS CORRECT
FOR THESE
MODELS.

MODELS 720, 721, 770, 771, 870 and 871



CONVENTIONAL ALIGNMENT, SEE SPECIAL SECTION OF VOL. 8