


UNDER CHASSIS



You will find Model 9022, Chassis 132.871 almost identical; while Model 9105, Chassis 132.875 uses type 6AQ5 output tube and has a record changer.